



HEX MACHINE SCREW NUTS								
Nominal Size or Basic Thread Diameter		F			G		H	
		Width Across Flats			Width Across Corners		Thickness	
		Basic	Max	Min	Max	Min		
0	0.0600	5/32	0.156	0.150	0.180	0.171	0.050	0.043
1	0.0730	5/32	0.156	0.150	0.180	0.171	0.050	0.043
2	0.0860	3/16	0.188	0.180	0.217	0.205	0.066	0.057
3	0.0990	3/16	0.188	0.180	0.217	0.205	0.066	0.057
4	0.1120	1/4	0.250	0.241	0.289	0.275	0.098	0.087
5	0.1250	5/16	0.312	0.302	0.361	0.344	0.114	0.102
6	0.1380	5/16	0.312	0.302	0.361	0.344	0.114	0.102
8	0.1640	11/32	0.344	0.332	0.397	0.378	0.130	0.117
10	0.1900	3/8	0.375	0.362	0.433	0.413	0.130	0.117
12	0.2160	7/16	0.438	0.423	0.505	0.482	0.161	0.148