


SQUARE MACHINE SCREW NUTS								
Nominal Size or Basic Thread Diameter		F			G		H	
		Width Across Flats			Width Across Corners		Thickness	
		Basic	Max	Min	Square			
Max	Min	Max	Min	Max	Min			
0	0.0600	5/32	0.156	0.150	0.221	0.206	0.050	0.043
1	0.0730	5/32	0.156	0.150	0.221	0.206	0.050	0.043
2	0.0860	3/16	0.188	0.180	0.265	0.247	0.066	0.057
3	0.0990	3/16	0.188	0.180	0.265	0.247	0.066	0.057
4	0.1120	1/4	0.250	0.241	0.354	0.331	0.098	0.087
5	0.1250	5/16	0.312	0.302	0.442	0.415	0.114	0.102
6	0.1380	5/16	0.312	0.302	0.442	0.415	0.114	0.102
8	0.1640	11/32	0.344	0.332	0.486	0.456	0.130	0.117
10	0.1900	3/8	0.375	0.362	0.530	0.497	0.130	0.117
12	0.2160	7/16	0.438	0.423	0.619	0.581	0.161	0.148



SQUARE NUTS									
Nominal or Basic Major Diameter of Thread		F			G		H		
		Width Across Flats			Width Across Corners		Thickness		
		Basic	Max	Min	Max	Min	Basic	Max	Min
1/4	0.2500	7/16	0.438	0.425	0.619	0.554	7/32	0.235	0.203
5/16	0.3125	9/16	0.562	0.547	0.795	0.721	17/64	0.283	0.249
3/8	0.3750	5/8	0.625	0.606	0.884	0.802	21/64	0.346	0.310
7/16	0.4375	3/4	0.750	0.728	1.061	0.970	3/8	0.394	0.356
1/2	0.5000	13/16	0.812	0.788	1.149	1.052	7/16	0.458	0.418
5/8	0.6250	1	1.000	0.969	1.414	1.300	35/64	0.569	0.525
3/4	0.7500	1-1/8	1.125	1.088	1.591	1.464	21/32	0.680	0.632
7/8	0.8750	1-5/16	1.312	1.269	1.856	1.712	49/64	0.792	0.740
1	1.0000	1-1/2	1.500	1.450	2.121	1.961	7/8	0.903	0.847
1-1/4	1.2500	1-7/8	1.875	1.812	2.652	2.458	1-3/32	1.126	1.062
1-1/2	1.5000	2-1/4	2.250	2.175	3.182	2.956	1-5/16	1.348	1.276