



<b>T - NUTS</b>							
Thread Size	H	Number of Prongs	G	F	A	T	Drill Size
	Barrel Height		Flange Diameter	Barrel Diameter	Prong Height	Material Thickness	
10-24	5/16	3	3/4	.243	7/32	.040	1/4
10-24	5/16	4	3/4	.243	7/32	.040	1/4
10-32	5/16	3	3/4	.243	7/32	.040	1/4
10-32	5/16	4	3/4	.243	7/32	.040	1/4
1/4-20	5/16	3	3/4	.305	7/32	.047	5/16
1/4-20	5/16	4	3/4	.305	7/32	.047	5/16
1/4-20	7/16	3	3/4	.305	5/16	.047	5/16
1/4-20	7/16	4	3/4	.305	1/4	.047	5/16
5/16-18	3/8	3	7/8	.390	1/4	.063	25/64
5/16-18	3/8	4	7/8	.390	1/4	.063	25/64
5/16-18	5/8	3	7/8	.390	5/16	.063	25/64
3/8-16	7/16	4	1	.440	11/32	.063	29/64